DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133

(707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-017054 Address: 333 Burma Road **Date Inspected:** 24-Sep-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Yu Dong Ping, Qiu Wen **CWI Present:** Yes No **Inspected CWI report:** Yes No N/A **Rod Oven in Use:** Yes No N/A Yes N/A N/A **Electrode to specification:** No Weld Procedures Followed: Yes No Yes N/A N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A Delayed / Cancelled:

34-0006 **Bridge No: Component: OBG/TOWER**

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

This Quality Assurance (QA) Inspector observed the following work in progress:

BAY 10, BIKE PATH (HSR1(B)-9343)

During random in process inspection this QA inspector observed that ZPMC personnel performing heat straightening on the weld joints of bike path. The QC monitoring HSR is identified Mr. Li Jun. The members are identified as OBG components and the weld designations reviewed are as follows.

BK004A1-032-009 BK004A-025

BAY 10 BIKE PATH

FCAW welding of weld joint 134 located on BK004A5-029. Welder is identified as 052075. ZPMC QC is identified as Mr. Ma Qian Li. The welding variables recorded by QC appeared to comply with WPS-B-T-2231-B-U2-F.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

FCAW welding of weld joint 135 located on BK004A5-029.

Welder is identified as 057180. ZPMC QC is identified as Mr. Ma Qian Li.

The welding variables recorded by QC appeared to comply with WPS-B-T-2231-B-U2-F.

FCAW welding of weld joint 135 located on BK004A5-030.

Welder is identified as 053116. ZPMC QC is identified as Mr. Ma Qian Li.

The welding variables recorded by QC appeared to comply with WPS-B-T-2231-B-U2-F.

TOWER FACADE SUBASSEMBLY

SMAW welding of weld joint 001 located on ND1-SFSA4-335A/B.

Welder is identified as 040268. ZPMC QC is identified as Mr. Wang Hao.

The welding variables recorded by QC appeared to comply with WPS-B-P-2114.

SMAW welding of weld joint 002 located on ND1-SFSA4-335A/B.

Welder is identified as 056364. ZPMC QC is identified as Mr. Wang Hao.

The welding variables recorded by QC appeared to comply with WPS-B-P-2114.

BAY 11 BIKE PATH

SMAW welding of weld joint 134 located on BK004A5-018.

Welder is identified as 040655. ZPMC QC is identified as Mr. Shao Hai Long.

The welding variables recorded by QC appeared to comply with WPS-B-P-2212-B-U2.

FCAW welding of weld joint 008 located on BK004A1-021.

Welder is identified as 053316. ZPMC QC is identified as Mr. Shao Hai Long.

The welding variables recorded by QC appeared to comply with WPS-B-P-2212-B-U2.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.





WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang: 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Gaikwad,Umesh	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer